

ROAD MASTER'S REPORT

For the month of February 2017

Roadwork:

1. Plowed and cindered as needed
2. Fairfield and Sheetz intersection had a sign that had been ran over. We pulled it out and took to Fairfield Inn.
3. Counted guide rails and posts for possible instillation on Harmony Hill.
4. Replaced 35 mph sign on Hillside other sign was bent.
5. Straightened street sign at intersection of Glen and Claverack.
6. Checked and cleaned all pipes on Old Sawmill.
7. Cleaned off both bridges Fall Run and Glen they had snow and ice built up. The drains were plugged this was done by hand.
8. Drove township roads with Vestal Asphalt for possible crack seal on our roads.
9. Took pipes that we pulled out last year that we had stockpiled at our Laning Creek property to Towanda Iron and metal as long as some scrap metal behind our building.

Trucks and Equipment:

1. Replaced spreader light on Truck 2.
2. Repaired RH plow headlight on Truck 2.
3. Tightened chains on cinder spreaders.
4. Checked all fluids in trucks.
5. Rotated cutting edges on both plows on Truck's 1 & 2.
6. While plowing snow check engine light came on truck 2 and it lost power. Took truck to Sherwood Groves they claim truck had sucked up water through the air box and it ruined the mass air flow sensor and throttle body. Township manager and I talked it over and figured if we did it

ourselves could save approximately \$500. The parts are on order through Wysox Napa.

7. Installed a new amber flasher on truck 3 and put the old one on truck 4. It did not have one.
8. Teledair came and updated GPS units in our trucks.
9. Washed trucks 1,2 and 3.
10. While hauling pipes to Towanda Iron and Metal truck 4 quit and would not start. We took it to Fulmers they claimed it needed a Cam Shaft Sensor. While it was there they noticed it needed a water pump talked it over with township manager. We agreed for them to fix it.

Office and Buildings:

1. Installed new light bulbs in main office.
2. The gutters on shop were leaking on the seams. We put some sealant on them.
3. We had a issue with fuel tank out back not having power called Mountain Lake Electric. The problem was a wire came loose in the fuse box. They noticed the main wire outside to the tank was not very safe we agreed for them to make it right.
4. Cleaned ditch out behind building for water run off.